

2410 Firmware Field


Updating Firmware for the 2410

Required Tools

- Latest autoloader firmware for the 2410. Locate this at www.rimage.com
- Gemini tool

Procedure for Rimage Producers and Catalyst.

1. Locate services in the windows search on the pc.




R I M A G E[®]


2. Stop the Rimage Production Services.



3. Locate the Gemini Utility in Windows search on the pc.



4. Launch the Utility and browse to the location you saved the firmware file that was downloaded from our website. Press the update firmware button.



RIMAGE®

5. When it is completed, restart the Rimage production server. Now the latest version should show in the Rimage system manager.

