

限用物質含有情況標示聲明書

Declaration of the Presence Condition of the Restricted Substances Marking

證書號碼／受理編號：(No.)

Certificate No / Application No.

商品標籤及商品檢驗標識：(Picture)

Product Label and Commodity Inspection Mark.

樣張及其標示位置：(Description and Picture)

Sample and its location

設備名稱： <u>自動光碟燒錄列印系統</u> ，型號（型式）：RAS32, Catalyst 6000 Equipment name Type designation (Type)						
單元 Unit	限用物質及其化學符號 Restricted substances and its chemical symbols					
	鉛Lead (Pb)	汞Mercury (Hg)	鎘Cadmium (Cd)	六價鉻 Hexavalent chromium (Cr ⁺⁶)	多溴聯苯 Polybrominated biphenyls (PBB)	多溴二苯醚 Polybrominated diphenyl ethers (PBDE)
印刷電路板配件(Printed Circuit Assemblies)	—	○	○	○	○	○
印刷電路板主要配件(Main Printed Circuit Assembly)	—	○	○	○	○	○
顯示器印刷電路板配件(Display Printed Circuit Assembly)	—	○	○	○	○	○
外接電(線)纜(External Cables)	○	○	○	○	○	○
內部電線(Internal Cables)	○	○	○	○	○	○
螺帽,螺釘,螺旋,墊圈,固定件 (Nuts, bolts, screws, washers, Fasteners)	○	○	○	○	○	○
電源供應器 (Power Supply)	—	○	○	○	○	○
風扇 (Fan)	○	○	○	○	○	○
金屬件 (Metalwork)	—	○	○	○	○	○
塑膠件 (Plastic work)	○	○	○	○	○	○
文件說明書 (Paper Manuals)	○	○	○	○	○	○
軟件光碟 (Software Disc)	○	○	○	○	○	○
<p>備考1. “超出0.1 wt %” 及 “超出0.01 wt %” 係指限用物質之百分比含量超出百分比含量基準值。 Note 1 : “Exceeding 0.1 wt %” and “exceeding 0.01 wt %” indicate that the percentage content of the restricted substance exceeds the reference percentage value of presence condition.</p> <p>備考2. “○” 係指該項限用物質之百分比含量未超出百分比含量基準值。 Note 2 : “○” indicates that the percentage content of the restricted substance does not exceed the percentage of reference value of presence.</p> <p>備考3. “—” 係指該項限用物質為排除項目。 Note 3 : The “—” indicates that the restricted substance corresponds to the exemption.</p>						