PrismPlus! Printer Firmware Release Notes

Firmware version

Version 5.202

Compatibility

- This firmware is compatible with a series 5 Prism*Plus!* printer, but it is not compatible with series 4 or non-USB printers.
- This firmware is not compatible with the 3-bin carousel AutoPrismPlus!.
- The printer requires a printer mode change in order to operate with a 4-bin AutoPrism*Plus!*. Refer to your user guide for details.

Changes

- Resolved an issue where the printer did not detect or resolve a failure to raise the print head.
- Resolved an issue where a problem with print speed control caused the printer to lock in slow mode, stall, and/or impair print quality.