

**6100, 7100, 8100, 6200, AutoPrinter III, Professional 3400, 3410, 2410 and 2000i**

零件项目(名称) (Component Name)	有毒有害物质或元素 (Hazardous Substances or Elements)					
	铅 Lead (Pb)	汞 Mercury (Hg)	镉 Cadmium (Cd)	六价铬 Chromium VI Compounds (Cr6+)	多溴联苯 Poly-brominated Biphenyls (PBB)	多溴二苯醚 Poly-brominated Diphenyl Ethers (PBDE)
印刷电路配件 (Printed Circuit Assemblies)	X	O	O	O	O	O
印刷电路主要配件 (Main Printed Circuit Assembly)	X	O	O	O	O	O
显示器印刷电路装配 (Display Printed Circuit Assembly)	X	O	O	O	O	O
外接电(线)缆 (External Cables)	O	O	O	O	O	O
内部线路 (Internal wiring)	O	O	O	O	O	O
螺帽,螺钉(栓),螺旋(钉),垫圈,紧固件 (Nuts, bolts, screws, washers, Fasteners)	O	O	O	O	O	O
电源供应器 (Power Supply)	X	O	O	O	O	O
风扇 (Fan)	O	O	O	O	O	O
金属制品[制造] (Metalwork)	X	O	O	O	O	O
塑胶制品[制造] (Plastic work)	O	O	O	O	O	O
文件说明书 (Paper Manuals)	O	O	O	O	O	O
软件光盘 (Software disc)	O	O	O	O	O	O
O: 表示该有毒有害物质在该部件所有均质材料中的含量均在 SJ/T 11363-2006标准规定的限量要求以下.						
O: Indicates that this toxic or hazardous substance contained in all of the homogeneous materials for this part is below the limit requirement in SJ/T11363-2006.						
X: 表示该有毒有害物质至少在该部件的某一均质材料中的含量超出 SJ/T 11363-2006标准规定的限量要求.						
X: Indicates that this toxic or hazardous substance contained in at least one of the homogeneous materials used for this part is above the limit requirement in SJ/T11363-2006.						